

August 23, 2018

Please find the following addendum to the below mentioned BID.

Addendum No.: 3

Bid#: 333-00-18-21-2

Project Name: Covington Library Renovation

Bid Due Date: Thursday, August 30, 2018

GENERAL INFORMATION:

- 1. For additional information, see enclosed letter from GVA Engineering, L.L.C. dated August 22, 2018 (3 pages).
- 2. Mold Report with additional information regarding testing results (referenced in Addendum No. 2) from SEMS, Inc. Southern Environmental Management & Specialties dated August 20, 2018 (38 pages).

QUESTIONS & ANSWERS:

Question #1: "can you please clarify where the plans reference resealing the existing windows is?"

Answer #1: Refer to notes on Demolition/Remedial Floor Plan on Sheet D101 and details and notes on sheet A602.

ATTACHMENTS:

- 1. Letter from GVA Engineering, L.L.C. dated August 22, 2018 (3 pages).
- 2. Limited Mold Assessment Report from SEMS, Inc. Southern Environmental Management & Specialties dated August 20, 2018 (38 pages).

<< End of Addendum No. 3 >>

GVA ENGINEERING, L.L.C.

2615 Edenborn Avenue, Suite C Metairie, Louisiana 70002 Phone (504) 780-9330 Fax (504) 780-9419

August 22, 2018

VIA E-Mail: eorgeron@burgdahlgraves.com

Burgdahl & Graves Architects Attn: Emily Orgeron 2550 Belle Chasse Highway, Ste. 130 Gretna, LA 70053

SUBJECT: St. Tammany Parish Library Covington Branch 310 W. 21st Ave. Covington, LA 70433 Renovations GVA Project No. 3742

Gentlemen:

Please include the following in your next addendum:

PERTAINING TO THE DRAWINGS

- Item No. 1. Sheet No. AC-2, HVAC Floor Plan In Vestibule 102, Electric Draft Barrier Heater EH-1 shall be Markel model DBT or equal. Heater shall be 9 feet long, 2250 watts, 208 volts, single phase, with integral tamper proof thermostat. Color selection by Architect.
- Item No. 2. Sheet No. E-3, Power & Special Systems Floor Plan Provide 2#12, 1#12(G) in 3/4"C from Electric Draft Barrier Heater EH-1 to a 20A, 2P toggle switch to be located adjacent to EH-1. Provide 2#12, 1#12(G) in 3/4"C from toggle switch to a 20A/2P circuit breaker to be installed in Panel ACR. The portion of raceway that is exposed, in Vestibule 102, shall be surface mounted raceway similar to Wiremold AL2000 (color as selected by Architect).
- Item No. 3. Sheet No. E-4, Panelboard Schedule In Panel ACR, remove the (2) 1-pole spaces and in lieu thereof, provide (1) 20A/2P circuit breaker for EH-1.

PRIOR APPROVAL OF MATERIALS

Listed below are manufacturers who are recognized as capable of producing materials, manufactured items, and articles of equipment equal to those specified. Equipment will be considered acceptable providing the equipment meets, or exceeds specification requirements, has the capacity and performance requirements, fits the space available to the satisfaction of the Architect, conforms in every respect with the applicable regulatory agencies and for lighting fixtures is also similar in appearance, construction and photometrics (photometric information shall be based on independent laboratory reports). Burgdahl & Graves Architects Attn: Emily Orgeron Project No. 3742 August 22, 2018 Page 2

Contractor shall submit for approval large scale drawings of proposed layouts and arrangements and samples of lighting fixtures when requested.

The listed prior approvals are not given with respect to any specific model, series, catalog number, etc. Suppliers are cautioned that before their equipment is actually approved, it will be incumbent upon them to demonstrate to the Architect that it is in fact equal to the requirements specified and conforms fully to all specification requirements.

MATERIAL/EQUIPMENT	MANUFACTURER
Water Closet	Gerber, Zurn
Urinal	Gerber, Zurn
Lavatories	Zurn
Faucets and Accessories	Moen
Water Hammer Arrestor	Watts
Cleanouts and Covers	Watts
Plumbing Fixture Carriers	Watts
Flush Valves	Moen
Water Cooler	Murdock
VRF & Ductless Split AC Units	Mitsubishi, Daikin, Samsung
F1, F1A, F1AE, F1E	Contech Lighting
F2, F2A	Lumium
F3	
Ė4	Advantage Environmental Lighting
F5	LSI
F6	
F7	
F8, F8A, F8B, F8C,F8D, F8F	
F9	Airey-Thompson
F10	LSI
Exit	LSI

T:\JOBS\3700's\3742\Correspondence\08-21-2018.ADENDUM ITEMS.BGA.EO.dcc.wpd

Burgdahl & Graves Architects Attn: Emily Orgeron Project No. 3742 August 22, 2018 Page 3

Lighting Controls Lutron

Sincerely,

GVA ENGINEERING, L.L.C.

Scott Oestriecher

SAO/aec



Limited Mold Assessment Report

St. Tammany Parish Library Covington Branch Library August 20, 2018 SEMS Project No.: 1008-0001



Prepared By: SEMS, INC.



11628 S. Choctaw Drive Baton Rouge, LA 70815 Phone: 225.924.2002 Fax: 225.924.2004 www.semsinc.net

August 20, 2018

Project No. 1008-0001

Ms. Kelly LaRocca Interim Director 1112 W. 21st Avenue Covington, Louisiana 70433 kelly@stpl.us

> Limited Mold Assessment Report St. Tammany Parish Library Covington Branch Library 310 W. 21st Avenue Covington, Louisiana 70433

Dear Ms. LaRocca:

The purpose of this report is to present the results of a limited mold assessment conducted on August 8, 2018 and post-cleaning verification testing conducted on August 15, 2018. This limited assessment was conducted in general accordance with SEMS proposal number P18-307 dated August 6, 2018 and SEMS change order for the project dated August 13, 2018. We understand this limited assessment was requested due to visible mold concerns in the Covington Branch Library prior to bids being accepted for an upcoming renovation of the building.

SEMS is pleased to offer industrial hygiene services to St. Tammany Parish Library. If you have any questions regarding this report or if we can offer additional occupational health and safety related services, please contact the undersigned below at 225-408-2809.

Sincerely, **SEMS, Inc.**

Phillip M. Bellan, J.D., CIH Industrial Hygiene Manager

yw. abuta

Roy Dowling, PhD, CIH, PE Senior Project Manager

TABLE OF CONTENTS

1.0	INTRODUCTION
1.1	SCOPE OF SERVICES
2.0	SITE DESCRIPTION
3.0	EVALUATION CRITERIA
3.1	SURFACE AND SWAB SAMPLES
3.2	BIOAEROSOL SAMPLES
4.0	RESULTS AND RECOMMENDATIONS
4.1	VISUAL OBSERVATION
4.2	MOISTURE LEVEL MEASUREMENTS 4
4.3	TAPE LIFT SAMPLING RESULTS
4.4	SPORE TRAP SAMPLING RESULTS
4.5	POST CLEANING VERIFICATION
4.6	RECOMMENDATIONS
5.0	GENERAL COMMENTS

ATTACHMENT A: LABORATORY ANALYTICAL REPORTS ATTACHMENT B: PHOTOGRAPHS ATTACHMENT C: INFRARED PHOTOGRAPHS ATTACHMENT D: SAMPLE LOCATION DIAGRAM

Limited Mold Assessment Report

St. Tammany Parish Library Covington Branch Library 310 W. 21st Avenue Covington, Louisiana 70433

SEMS Project Number: 1008-0001 August 20, 2018

1.0 INTRODUCTION

Southern Environmental Management Services, Inc. (SEMS) conducted limited mold assessment at the Covington Branch Library at the above referenced location. This assessment was requested because of visible mold concerns at the top of the vaulted ceilings in the main area of the branch library. Following the initial, limited mold assessment, St. Tammany Parish Library personnel cleaned the area of concern and then requested post-cleaning verification samples be collected.

1.1 SCOPE OF SERVICES

The scope of this project included a limited initial mold assessment and post-cleaning verification testing. SEMS mobilized, Mr. Phillip Bellan, a certified industrial hygienist (CIH) for both the initial and post-cleaning testing.

During the initial inspection, Mr. Bellan conducted an initial walk through of the building and identified the suspected visible mold of concern. Mr. Bellan designated the area of the library which housed the books the library loans out as the complaint area and the office space and computer area of the library as non-complaint areas based on this walk through and the location of suspected mold growth. Mr. Bellan collected direct-reading moisture measurements from the complaint area of the building. He also collected tape lift samples of the visible suspected mold growth on the vaulted ceilings in the complaint area. He also collected spore trap type samples of air from the complaint and non-complaint areas of the building as well as the building interior, so he could assess the building indoor air quality. The HVAC system was inspected, and thermal imaging was conducted.

During the post-cleaning verification testing, Mr. Bellan took swab samples over a 1 square foot area of the vaulted ceilings in the complaint area where suspected mold growth was confirmed by the initial sampling.

2.0 SITE DESCRIPTION

The Covington Branch Library is located at 310 W. 21st Avenue in Covington, Louisiana. The branch was the former home of the St. Tammany Parish Library administrative offices. These offices have since moved to another building on 21st Avenue. The Covington Branch library has two distinct areas to the building. The main area is the book storage area where books are held for lending purposes. This area has large vaulted ceilings of approximately 20 feet in height. These ceilings are composed of gypsum board sheets which meet at a sharp angle. The sheets are caulked

together at the apex. Over time, the building has shifted slightly and caused this caulk to crack in numerous places.

The other area of the library where the former administrative offices were located has several offices, a computer room, meeting rooms, and break rooms. This area of the library has ceilings of approximately 10 feet in height.

The main area and the former administrative office area each have their own heating, ventilation, and air conditioning system (HVAC). Each area has two air handling units (AHU).

3.0 EVALUATION CRITERIA

Since many building materials can provide a source of food for mold, water is the limiting factor in minimizing the potential for its growth. Therefore, visible mold, excessive dirt, and waterdamaged building materials should not be observed. When these conditions are observed, it indicates a need to conduct additional assessment, cleaning, or remediation activities to minimize the potential for mold-related issues. When visible suspected mold growth is seen, the best practice is to allow a Louisiana licensed mold remediation contractor to perform the cleaning or remediation work.

Elevated mold concentrations in indoor environments can occur when excessive moisture and a food source are present, especially in closed or concealed areas with minimal air disturbance. The cellulose in the paper surfacing of drywall or gypsum board, provides an adequate food source for the growth of many types of mold. There are no current regulatory standards that limit moisture levels in walls or building materials, but the data can be valuable when results from different locations are compared. Onsite moisture measurements are obtained using a direct-reading instrument. Results from similar materials in non-suspect locations are compared and used to assess the likelihood of mold growth conditions in suspect or historically water-damaged materials.

All mold samples should be evaluated by a third-party laboratory accredited by the American Industrial Hygiene Association (AIHA).

3.1 SURFACE AND SWAB SAMPLES

Surface samples may be analyzed by direct microscopic examination. The primary purpose of a direct microscopic examination is to determine whether or not mold is growing on the surface sampled, and if so, what kinds of molds are present. This type of analysis may identify "marker" genera that may be indicative of indoor mold growth. The presence of biological materials on a surface is not a direct indication of what may be in the air.

3.2 BIOAEROSOL SAMPLES

Microorganisms are ubiquitous in the environment and have specific requirements for survival and growth. In the indoor environment, microorganisms often exist as bioaerosols. Bioaerosols are airborne particles that are living or were released from a living organism. At present, no mandatory regulations or standards have been established for the maximum allowable concentration of bioaerosols such as mold spores. Although bioaerosols have not been conclusively associated with adverse health effects commonly noted in building-related complaints (e.g., mucous membrane

irritation, headache, and fatigue) some studies and case histories have shown correlations between these symptoms and microbial contamination of humidification and cooling systems.

The spore trap sampling method used for airborne mold sampling can determine total fungal spore concentrations per cubic meter of air. High variability in mold spore concentrations will exist in different geographic locations, during different seasons and weather patterns, and over the course of a given day. As a general rule, indoor mold spore concentrations in a typical, HVAC-supplied building are usually less than, but qualitatively similar to, spore concentrations found in the outside environment. To better interpret the results of airborne mold sampling, a comparative sampling strategy is employed where complaint area samples are collected and compared to non-complaint area samples. Additionally, outdoor (exterior) ambient air sampling is typically conducted as well to document the type of concentrations of mold spore types present in the outdoor air.

Over the past several years, industrial hygienists and researchers from several governmental and non-governmental agencies have collectively gathered a significant body of data from air, dust, and surface samples during both investigative studies and mold remediation projects. The recommended criteria for evaluating airborne mold concentrations which have emerged from peerreviewed publications include the following:

- The mold concentration in indoor or complaint air should generally be quantitatively lower than, but qualitatively similar to, that of outdoor or non-complaint air.
- The presence of one or more fungal species at significant levels indoors but not outdoors is evidence of indoor amplification (i.e., biological growth occurring in the indoor environment).
- Pathogenic (disease-causing) and toxigenic (toxin-producing) molds should not be present in quantities indicative of indoor amplification.

4.0 **RESULTS AND RECOMMENDATIONS**

4.1 VISUAL OBSERVATION

Visual observation of the main library area which is designated as the complaint area, showed approximately 50 square feet of suspected surface mold growth on the vaulted ceilings. This growth was occurring at places where the caulking at the apex of the ceiling was deteriorated or missing which allowed hot air from the building exterior to condense when it met the cool air in the building interior.

The visual observations were confirmed by infrared photography which showed the temperature differential at the apex of the roof of the main library area.

4.2 MOISTURE LEVEL MEASUREMENTS

Moisture level measurements were collected around the vaulted ceiling area near the suspected mold growth. These readings indicated the gypsum board material in this location was dry and that water intrusion from the roof was not a concern and that likely the mold growth was superficial only and caused by condensation. The moisture readings were collected using a General[®] MMD4E moisture meter. This moisture meter has two prongs which can be inserted into building materials

to measure the electrical conductivity between them which can be interpreted by the device as moisture content.

4.3 TAPE LIFT SAMPLING RESULTS

Two tape lift samples were collected from areas of suspected visible mold growth. These samples were analyzed by microscopic examination of fungal spores, hyphae, and other particulates. The results of the tape lift samples are presented in the table below:

Tupe Life Sumple Results						
Sample Name and Date	Location	Spore Type Present				
1008-0001-01 / 8-8-18	Non-Fiction Ceiling	Cladosporium – Abundant Hyphal Fragments – Moderate				
1008-0001-02 / 8-8-18	Children Ceiling	Cladosporium – Abundant Hyphal Fragments – Moderate				

Tape Lift Sample Results	Tape	Lift	Sample	Results
--------------------------	------	------	--------	---------

The tape lift sampling confirmed that the suspected visible growth on the vaulted ceiling was mold growth.

4.4 SPORE TRAP SAMPLING RESULTS

Five spore trap samples were collected from the Covington Branch Library site. One sample was collected in the main area, designated the complaint area. One sample was collected in the former admin office area, designated the non-complaint area. Two samples were collected from different entrances outside the building and one quality control blank was collected for analysis.

Spore trap samples are collected by drawing air into a cassette specially designed to capture airborne fungal spores along with other particulates. The spore trap samples are analyzed by microscopic examination of fungal spores, hyphae, and other particulates. The results are then compared by examining the interior versus the exterior samples and the complaint versus the non-complaint samples. Results of the sampling is presented in the table below:

	<u> </u>				
Sample Name	1008-	1008-	1008-0001-	1008-	1008-
	0001-03	0001-04	05	0001-06	0001-07
Location	Outside 1:	Complaint:	Non-	Outside 2:	Blank
	Main	Non-	Complaint:	Employee	
	Entrance	Fiction	Computer	Entrance	
			Room		
Taxa	Counts/m ³				
Alternaria	20	-	-	13	-
Arthrinium	7	-	-	-	-
Ascospores	17400	-	47	10593	-
Aspergillus/Penicillium	153	1067	-	167	-
Basidiospores	480	7	-	353	-
Bipolaris/Dreschslera	7	-	-	13	-
Cercospora	7	-	-	-	-
Cladosporium	587	400	-	427	-
Curvularia	7	7	7	40	-
Helicomyces	-	-	-	7	-
Hyphal Fragments	47	47	13	53	-
Mildew	7	-	-	-	-
Nigrospora	13	-	7	33	-
Paecilomyces	87	-	-	-	-
Periconia/Myxomycetes/Smuts	13	7	-	13	-
Pithomyces/Ulocladium	7	-	-	-	-
Rusts	100	-	-	-	-
Spegazzinia	33	-	-	-	-
Torula	7	-	-	-	-
Total Results	18982	1535	74	11712	-

Spore Trap Sample Results

The bioaerosol sampling results indicate that indoor air in the library is improved compared to the air outside in all taxa of mold recognized. Further the complaint and non-complaint areas are similar in air quality. The complaint area did show less of a reduction in *Cladosporium* spores and this is likely due to the active *Cladosporium* colony growing on the ceiling in the complaint area.

4.5 POST CLEANING VERIFICATION

Following this survey, St. Tammany Parish Library personnel cleaned the affected areas with Fiberlock ShockwaveTM, an EPA approved mold and bacteria disinfectant. Following this cleaning SEMS re-mobilized to the site to conduct post cleaning verification testing. During this testing a 1 square foot area of the ceiling was swabbed utilizing a sterile swab as visible mold was no longer present.

Two areas were swabbed in similar regions as the tape lift samples were collected. The swabs were then analyzed by microscopic examination of fungal spores, hyphae, and other particulates. The results of the swab samples are presented in the table below:

Sample Name and Date	Location	Spore Type Present
PC-01 / 8-15-18	Non-Fiction Ceiling	No Mold Detected
PC-02 / 8-15-18	Children Ceiling	No Mold Detected

Swab Sample Results

The post clearance verification testing confirms the post-cleaning visual observation that no mold is detected.

4.6 **RECOMMENDATIONS**

SEMS recommends the following:

- Fix missing or deteriorated caulk in vaulted ceiling area of the building in order to prevent surface mold from re-occuring
- Continue to change HVAC filters every 4 weeks
- Following planned renovation, have HVAC balanced and serviced by licensed HVAC technician.

5.0 GENERAL COMMENTS

This limited mold assessment was conducted in a manner consistent with the level of care and skill ordinarily exercised by members of the profession currently practicing under similar conditions in the same local. This assessment is conducted in general accordance with our referenced proposal and industry consensus guidelines established by the American Industrial Hygiene Association (AIHA) in Assessment, Remediation, and Post-Remediation Verification of Mold in Buildings – AIHA Guideline 3-2004 and the American Conference of Governmental Industrial Hygienists (ACGIH), Bioaerosols: Assessment and Control, 1999. The results, findings, conclusions, and recommendations expressed in the report are based on conditions observed during our survey of the selected area on the property. The information contained in this report is relevant to the date(s) on which the survey was performed and should not be relied upon to represent conditions at a later date. This report has been prepared on behalf of and for the exclusive use of our Client which the report is addressed and for their specific project the report was requested. This report is not a bidding document. Contractors and consultants who review this document at a later date must draw their own conclusions regarding further investigation or remediation deemed necessary. SEMS does not warrant the work of regulatory agencies, laboratories, or third parties who supplied information which may have contributed to the preparation of this report. Nor warranty, express or implied is made.

ATTACHMENT A ANALYTICAL LABORATORY REPORT



2033 Heritage Park Dr, Oklahoma City, OK 73120 | 1.800.822.1650

Microbiology Analytical Report (Results)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc	
Date Received:	08/09/2018		11628 S. Choctaw Dr Paton Pougo LA 70815	
Received By:	Travis Miller		Baton Rouge, LA 70815	
Analyzed By:	Terry Harrison			
Date Analyzed:	08/09/2018	Account Number:	C187	
Methodology:	Bulk, Qualitative NonCulturable,	Project:	Covington Branch Library	
	MM003, MM004, MM005	Location:	310 W 21 ave. Covington, LA	
AIHA ID Number:	101352	Project No:	1008-0001	

QuanTEM Sample ID	297694-001	297694-002		
Client Sample ID	1008-0001-01	1008-0001-02		
	Results	Results		
Cladosporium	Abundant	Abundant		
Hyphal Fragments	Moderate	Moderate		
Comments				



2033 Heritage Park Dr, Oklahoma City, OK 73120 1.800.822.1650

Microbiology Analytical Report (Signature Page)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc	
Date Received:	08/09/2018		11628 S. Choctaw Dr Paton Pougo I A 70815	
Received By:	Travis Miller		Batoli Kouge, LA 70815	
Analyzed By:	Terry Harrison			
Date Analyzed:	08/09/2018	Account Number:	C187	
Methodology:	Bulk, Qualitative NonCulturable,	Project:	Covington Branch Library	
	MM003, MM004, MM005	Location:	310 W 21 ave. Covington, LA	
AIHA ID Number:	101352	Project No:	1008-0001	

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA-LAP, LLC. or any agency of the U.S. Government.

Approved: Jawen Comeren

Lauren Cameron, Technical Manager



2033 Heritage Park Dr, Oklahoma City, OK 73120 | 1.800.822.1650

Microbiology Analytical Report (Results)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc	
Date Received:	08/09/2018		11628 S. Choctaw Dr Paton Pougo LA 70815	
Received By:	Travis Miller		Batoli Rouge, LA 70815	
Analyzed By:	Terry Harrison			
Date Analyzed:	08/09/2018	Account Number:	C187	
Methodology:	Spore Trap, Quantitative NonCulturable,	Project:	Covington Branch Library	
	MM001	Location:	310 W 21 ave. Covington, LA	
AIHA ID Number:	101352	Project No:	1008-0001	

QuanTEM Sample ID	297694-003	297694-004	297694-005	297694-006	297694-007	
Client Sample ID	1008-0001-03	1008-0001-04	1008-0001-05	1008-0001-06	1008-0001-07	
Volume (L)	150	150	150	150	0	
Detection Limit	7	7	7	7	0	
	Results	Results	Results	Results	Results	
	Counts/m ³					
Alternaria	20			13		
Arthrinium	7					
Ascospores	17400		47	10593		
Aspergillus/Penicillium Group	153	1067		167		
Basidiospores	480	7		353		
Bipolaris/Drechslera Group (2)	7			13		
Cercospora	7					
Cladosporium	587	400		427		
Curvularia	7	7	7	40		
Helicomyces				7		
Hyphal Fragments	47	47	13	53		
Mildew	7					
Nigrospora	13		7	33		
Paecilomyces	87					
Periconia/Myxomycetes/Smuts	13	7		13		
Pithomyces/Ulocladium	7					
Rusts	100					
Spegazzinia	33					
Torula	7					
No Mold Detected					Х	
Total Results (Counts/m ³)	18982	1535	74	11712		
Percent Coverage (%)	5	3	2	5	1	
Comments					No Mold Detected	



2033 Heritage Park Dr, Oklahoma City, OK 73120 | 1.800.822.1650

Microbiology Analytical Report (Counts)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc	
Date Received:	te Received: 08/09/2018		11628 S. Choctaw Dr Patan Pauga I A 70815	
Received By:	Travis Miller		Baton Rouge, LA 70813	
Analyzed By:	Terry Harrison			
Date Analyzed:	08/09/2018	Account Number:	C187	
Methodology:	Spore Trap, Quantitative NonCulturable,	Project:	Covington Branch Library	
	MM001	Location:	310 W 21 ave. Covington, LA	
AIHA ID Number:	101352	Project No:	1008-0001	

QuanTEM Sample ID	297694-003	297694-004	297694-005	297694-006	297694-007	
Client Sample ID	1008-0001-03	1008-0001-04	1008-0001-05	1008-0001-06	1008-0001-07	
Volume (L)	150	150	150	150	0	
	Counts	Counts	Counts	Counts	Counts	
Alternaria	3			2		
Arthrinium	1					
Ascospores	2610		7	1589		
Aspergillus/Penicillium Group	23	160		25		
Basidiospores	72	1		53		
Bipolaris/Drechslera Group (2)	1			2		
Cercospora	1					
Cladosporium	88	60		64		
Curvularia	1	1	1	6		
Helicomyces				1		
Hyphal Fragments	7	7	2	8		
Mildew	1					
Nigrospora	2		1	5		
Paecilomyces	13					
Periconia/Myxomycetes/Smuts	2	1		2		
Pithomyces/Ulocladium	1					
Rusts	15					
Spegazzinia	5					
Torula	1					



2033 Heritage Park Dr, Oklahoma City, OK 73120 1.800.822.1650

Microbiology Analytical Report (Signature Page)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc
Date Received:	08/09/2018		11628 S. Choctaw Dr Paton Pougo I A 70815
Received By:	Travis Miller		Batoli Kouge, LA 70815
Analyzed By:	Terry Harrison		
Date Analyzed:	08/09/2018	Account Number:	C187
Methodology:	Spore Trap, Quantitative NonCulturable,	Project:	Covington Branch Library
	MM001	Location:	310 W 21 ave. Covington, LA
AIHA ID Number:	101352	Project No:	1008-0001

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

(1)Small, single-celled, unidentifiable mold spores (2)Also includes spores from Exosporium, Exserohilum and Helminthosporium

Percent coverage = amount of particulate matter. With 25-50% coverage, results may be underestimated; with 50-70% coverage, results will be underestimated; with >70% coverage, slides are designated overloaded (too dirty to count). The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA-LAP, LLC. or any agency of the U.S. Government.

Approved: James Comeser

Lauren Cameron, Technical Manager



MICROBIOLOGY CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502

Page	1	of
Page	1	ot

	For Lab Use Unly				
L A B O R A T O R I E S www.QuanTEM.com	Lab No. <u>~ 4 76 77</u> Accept Reject				
Contact Information			Project In	nformation	Report Results (☑ one box)
Company: SEMS, Inc.	Phone: 225-408-2809	Project Name:	ovinsten	Branch Library	QuanTEM Website
Contact: Phillip Bellan	Cell Phone: 225-588-9066	Project Location:	310 W 21	ave lovindon. LA	Email pbellan@semsinc.net
Account #: C187	E-mail: pbellan@semsinc	.net Project ID: 10	08-000 1	,,,,	Other
SAMPLED BY: Name: Phillip Bellan	Date: 8-8-18	P.O. Number:	1 000-80	<i>21</i>	
RELINQUISHED BY	DATE & TIME	VIA		RECEIVED BY	DATE & TIME
m	8-8-118-16:00 F	edex	T'	M. 18-8-9 9:45	
			-		
	REQUESTED SERVICES	(Please 🗹 the Ap	ppropriate Bo>	(es)	
Fungal Analysis (non-culture) Fungal Analy	sis (non-culture) Fung	al Analysis (cultu	ure based)	Bacterial Analysis	TURNAROUND TIME
Spore Trap Bulk/Swab		mpaction Plate		Water Screen	Rush
Spore Trap (Detailed) Bulk/Swab (Qu	iantitative)	Sedimentation Plate		Sewage Screen	Same Day
Tape Lift Other (Specify	r in Comments)	Bulk/Swab - Genus ID	Γ	Heterotrophic Plate Count	24 - Hour
Tape/Lift (Quantitative)		Bulk/Swab - Genus ID &	Enumer.	Heterotrophic Plate count with ID	
		Other (Specify in Comm	(Specify in Comments) Other (Specify in Comments)		14 - Day (Cultures)
No. Sample ID Descr (10 Characters Max)	iption	Volume / Area (as applicable)		Media / Comments / I	Notes
1 1008-0001-01 They lift top van He.	l ceiling non fiction	≈2"x2"	tope life /	69.9° F @ sand-	locolta
2 -of Tage life top vaulter	ceilin chidren.	2 11	1. 1	11 @ samply	locatio
3 -03 outside 1: Front-	doo-	150L .	air-o-cell/	77°F	11 C C
4 - 04 complaint i adult f	iction / teen section	150 L	11 1	64.4°F	
5 -05 non-condaint: public	computer room	150 L	11 /	63.6°F	
6 -06 outside 2: outside	employer extense	150L	N /	74.6F	
7 -07 Blank		-	19		
8					~
9	10 C				
10					

SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup" Please Note - UPS and USPS are NOT available for Saturday Delivery



2033 Heritage Park Dr, Oklahoma City, OK 73120 | 1.800.822.1650

Microbiology Analytical Report (Results)

QuanTEM Lab ID: Date Received: Received By: Analyzed By:	298002 08/16/2018 Travis Miller Terry Harrison	Client:	SEMS, Inc 11628 S. Choctaw Dr Baton Rouge, LA 70815
Date Analyzed:	08/16/2018	Account Number:	C187
Methodology:	Swab, Qualitative NonCulturable,	Project:	Covington Library
	MM003, MM004, MM005	Location:	310 S. 21 Covington, LA
AIHA ID Number:	101352	Project No:	1008-0001

QuanTEM Sample ID	298002-001	298002-002	298002-003		
Client Sample ID	PC-01	PC-02	PC-03		
	Results	Results	Results		
No Mold Detected	Х	Х	Х		
Comments	No Mold Detected	No Mold Detected	No Mold Detected		



2033 Heritage Park Dr, Oklahoma City, OK 73120 1.800.822.1650

Microbiology Analytical Report (Signature Page)

QuanTEM Lab ID:	298002	Client:	SEMS, Inc
Date Received:	08/16/2018		11628 S. Choctaw Dr Paton Pougo I A 70815
Received By:	Travis Miller		Baton Rouge, LA 70815
Analyzed By:	Terry Harrison		
Date Analyzed:	08/16/2018	Account Number:	C187
Methodology:	Swab, Qualitative NonCulturable,	Project:	Covington Library
	MM003, MM004, MM005	Location:	310 S. 21 Covington, LA
AIHA ID Number:	101352	Project No:	1008-0001

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA-LAP, LLC. or any agency of the U.S. Government.

Approved:

Robin Brady Naik, Analyst



MICROBIOLOGY CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502

Page 1 of <u>1</u>

-

1	(800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058							FO							
LABORATORIES www.QuanTEM.com LEGAL DOCUMENT - PLEASE PRINT LEGIBLY							Lab	No.	Accept	Reject					
		Conta	act l	nformation					Project	t Inf	ormation	Rep	oort R	esults (🗹	one box)
Comp	any: SEMS, Inc.				Phone: 225-408-2	809		Project Name:	Covintor	L	OTH		Qua	anTEM We	ebsite
Conta	ct: Phillip Bellan				Cell Phone: 225-588-9	066		Project Location	×310 5.	2	1 Courts CA		Em	ail <u>pbellan@</u>	semsinc.net
Accou	Int #: C187				E-mail: pbellan@se	emsino	c.net	Project ID:	1008-0	00	1		Oth	ner	
Sam	PLED BY: Name: Phil	lip B.	ello	~	Date: 8-15-18			P.O. Number:	008-0	00	l				
	RELINQU	ISHED BY			DATE & TIME			VIA			RECEIVED BY			DATE 8	& TIME
1	Wh				8-15-18 /9:00	F	ele	4							
					REQUESTED SERV	ICES	(Ple	ase 🗹 the /	Appropriate B	oxe	es)				
Fu	ngal Analysis (non-c	ulture)	Fı	ungal Analys	sis (non-culture)	Fung	gal A	nalysis (cul	ture based)		Bacterial Analysis		TUF	RNAROUN	ND TIME
	Spore Trap		\times	Bulk/Swab			Impac	tion Plate			Water Screen			Rush	
	Spore Trap (Detailed)			Bulk/Swab (Qu	iantitative)		Sedim	entation Plate			Sewage Screen		×	Same Day	
	Tape Lift			Other (Specify	r in Comments)		Bulk/S	wab - Genus ID		Γ	Heterotrophic Plate Count		H	24 - Hour	
	Tape/Lift (Quantitative)						Bulk/S	wab - Genus ID	& Enumer.		Heterotrophic Plate count with ID		H	5 - Day	
		-			Ĩ		Other	(Specify in Com	iments)		Other (Specify in Comments)			14 - Day (Cultures)
No.	Sample ID (10 Characters Max)			Descri	iption		Vol (as	ume / Area applicable)		11	Media / Comments /	Note	S		
1	PC-01	Non-f	idi	in 811 0	Nrr Ceiling		1	Saft.	post de	chi	, -no visitto mold	Jer	tecto	1	
2	PL-02	chi Ha	inc	ave	ceilin		1	Sa fL.	11		21				
3	P1-03	Black	h					_	-					<i>4</i> .	
4															
5									8						
б					i.										
7															
8															
9															
10															

SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup" Please Note - UPS and USPS are NOT available for Saturday Delivery

ATTACHMENT B PHOTOGRAPHS



PHOTOGRAPHIC DOCUMENTATION



View of exterior of Covington Branch Library



View of visible mold growth sampled as 1008-0001-02



View of visible mold growth sampled as 1008-0001-01



View of pre-calibration for mold air sampling



PHOTOGRAPHIC DOCUMENTATION



View of sample 1008-0001-03 building exterior at main entrance



View of sample 1008-0001-05 non-complaint area



View of sample 1008-0001-04 complaint area



View of sample 1008-0001-06 building exterior at employee entrance



PHOTOGRAPHIC DOCUMENTATION



View of post-calibration for mold air sampling



View of complaint area ceiling with no visible mold



View of HVAC AHU on initial visit



View of example sample location for post-cleaning sampling

ATTACHMENT C INFRARED PHOTOGRAPHS



Parameters			
Emissivity 0.95			
Refl. temp.	68 °F		

8/8/2018 3:36:05 PM



8/8/2018 3:36:05 PM





Parameters			
Emissivity 0.95			
Refl. temp.	68 °F		

8/8/2018 3:36:36 PM



8/8/2018 3:36:36 PM





Parameters				
Emissivity	0.95			
Refl. temp.	68 °F			



8/8/2018 3:37:03 PM





Parameters	
Emissivity	0.95
Refl. temp.	68 °F

8/8/2018 3:37:14 PM



8/8/2018 3:37:14 PM





Parameters		
Emissivity	0.95	
Refl. temp.	68 °F	

8/8/2018 3:37:29 PM



8/8/2018 3:37:29 PM





Parameters		
Emissivity	0.95	
Refl. temp.	68 °F	



8/8/2018 3:37:46 PM





Parameters		
Emissivity	0.95	
Refl. temp.	68 °F	

8/8/2018 3:38:35 PM



8/8/2018 3:38:35 PM





Parameters		
Emissivity	0.95	
Refl. temp.	68 °F	

8/8/2018 3:38:49 PM



8/8/2018 3:38:49 PM





Parameters		
Emissivity	0.95	
Refl. temp.	68 °F	

8/8/2018 3:38:56 PM °F 72.9 1 <





Parameters		
Emissivity	0.95	
Refl. temp.	68 °F	

8/8/2018 3:39:08 PM



8/8/2018 3:39:08 PM





Parameters		
Emissivity	0.95	
Refl. temp.	68 °F	

8/8/2018 3:51:18 PM



8/8/2018 3:51:18 PM



FLIR0028.jpg

FLIR C3

720121777



Parameters		
Emissivity	0.95	
Refl. temp.	68 °F	

8/8/2018 3:51:30 PM



8/8/2018 3:51:30 PM



FLIR0029.jpg

FLIR C3

720121777

ATTACHMENT D SAMPLE LOCATION DIAGRAM





August 17, 2018

Please find the following addendum to the below mentioned BID.

Addendum No.: 2

Bid#: 333-00-18-21-2

Project Name: Covington Library Renovation

Bid Due Date: Thursday, August 30, 2018

GENERAL INFORMATION:

- 1. A Mandatory Pre-Bid Conference was held on August 1, 2018, 10:00 A.M. at the site. Pre-Bid Sign-In Sheets (2 total) are attached. The following matters were discussed:
 - Meeting included introduction of St. Tammany Parish Facilities and Library Department personnel, library staff, and design team.
 - Technical questions shall be in written form and forwarded directly to Rebecca Miller at St. Tammany Parish Procurement Department at rmiller@stpgov.org.
 - Construction schedule is 240 calendar days per project manual.
 - Per bid documents, project includes two additive alternates. Additive Alternate No. 1 includes Elastomeric Coating of Exterior Plaster, Stone, and Concrete. Additive Alternate No. 2 includes a new Heat Recovery VRF HVAC System.
 - The interior renovation includes, but is not limited to, new finishes throughout, expanded ADA restrooms, minor structural work, new LED light fixtures, and new HVAC system.
 - The exterior renovation includes, but is not limited to, new roof, waterproofing all exterior windows, and new mechanical yards.
 - Contractor to thoroughly read Specification Section 01040 "Project Coordination/Contractor's Use of Premises". Building/site will not be occupied during construction but specific shelving units will remain in place per notes on Cover Sheet of drawings.
 - Power for hand tools and water are available for use on the site, but Contractor is required to provide his own temporary toilet facilities.
 - Contractor, subcontractors, and all construction related personnel may park in library parking lots. If parking off site, contractor is responsible for following all local parking and zoning ordinances.



- See notes on Sheet D101 of drawings for staging and construction fence requirements. Contractor responsible for securing staging areas and protecting existing trees and vegetation.
- Contractor will have full access to the site at all times. Owner will hand over keys to Contractor at the start of construction.
- Contractor, subcontractors, and all construction related personnel shall be identified at all times with a company shirt or badge.
- The library is immediately adjacent to a residential area. Contractor is responsible for following all local zoning laws, noise ordinances, etc.
- Conference concluded with bidders walking the site to verify conditions.
- Should any contractor, subcontractor, or manufacturer need to visit the site, please coordinate with Library Maintenance Supervisor John Bennet. He can be reached at (985) 778-1821, (985) 809-9184, or john@stpl.us.
- Delete Sheet D101 from Section 11 Drawings and replace with revised Sheet D101 (attached). In Detail 1 Demolition / Remedial Floor Plan: Door to Corridor 132 from Meeting Room 139 (indicated as Door Tag 16 on Sheet A101) shall be dashed and called to be removed with frame to remain.
- 4. Delete Sheet A602 from Section 11 Drawings and replace with the revised Sheet A602 (attached). Key Note 15 was deleted in its entirety and replaced with the following:

15. 2-1/2" WIDE 16 GA. STAINLESS STEEL ANCHOR STRAP POWDERCOATED TO MATCH WINDOW TRIM CAP. PROVIDE ANCHOR STRAP AT EVERY VERTICAL FRAMING MEMBER (JAMBS, INTERMEDIATE MULLIONS, ETC.).

5. For additional items, see attached letter from GVA Engineering, L.L.C. dated August 7, 2018 (2 pages).

Listed below are manufacturers who or whose agents have requested prior approvals on this Project, and who are recognized as being capable of producing equal materials, manufactured items, and articles of equipment to that specified. An item will be considered acceptable providing it is submitted in accordance with Project Manual criteria and meets or exceeds all specification requirements (including required warranties), fits in the space available to the satisfaction of the Architect, and conforms in every respect with applicable regulatory agencies. During shop drawing phase, Architect will review and act upon the submittal of specific products intended for use, which should consist of detailed back-up literature (as previously reviewed/approved by Contractor) which confirms full compliance with specifications.



- 6. Section 08413 Interior Aluminum Entrances and Window Systems: Tubelite Inc.
- 7. Section 15650 Heating, Ventilating, and Air Conditioning Control Systems: Trane Controls
- 8. For additional manufacturers, see enclosed letter from GVA Engineering, L.L.C. dated August 7, 2018 (2 pages).
- 9. For additional manufacturers, see enclosed letter from GVA Engineering, L.L.C. dated August 10, 2018 (2 pages).

QUESTIONS & ANSWERS:

Question #1: "NORTHERN FRAME IN THE GENEALOGY ROOM #104 DOES NOT HAVE ANY FRAME NOR DOOR DESIGNATION. IS IT EXISTING?"

Answer #1: Per the Demolition/Remedial Floor Plan on Sheet D101, this door and frame are existing.

Question #2: "ALSO WESTERLY FRAME AND DOOR OUT OF VESTIBULE #102 AGAIN DOES NOT HAVE ANY DESIGNATION. IS THIS ALSO EXISTING?"

Answer #2: Per the Demolition/Remedial Floor Plan on Sheet D101, this door and frame are existing.

Question #3: "It seems the products specified by GVA Engineering, for the under carpet cabling are no longer available. The manufacturer TE was purchased by Commscope and they are no longer making these products available. Would it be possible to obtain some clarification as to a redesign for the communications cabling."

Answer #3: No, all products and components of the undercarpet cabling system are available.

Question #4: Are the exterior windows being removed for the waterproofing?

Answer #4: No, it is not necessary to remove windows to perform the contract work.



Question #5: Is there a "mold report" for the building? There is "mold on the ceiling above the penguin".

Answer #5: Yes. A preliminary report is attached. St. Tammany Parish had the section of ceiling tested, cleaned, and retested and the area is 100% normal. Contractor responsibility for work at the ceiling shall remain as shown in the Contract Documents.

Question #6: Key Note 28 on Sheet A201 talks about caulking 6 inches at the jamb. Does that mean only 6 inches at each jamb or for the whole sill because the difference between the two could be 400 linear feet of caulking?

Answer #6: As described in the note and referenced on the elevations, <u>where plaster wall</u> <u>transitions to cast stone sill via copper flashing</u>...caulk lines shall extend 6" from jamb. This condition occurs only at plaster to stone sill, where specifically indicated with Key Note.

Question #7: For insurance purposes, what is the building square footage?

Answer #7: Per the original project drawings, the enclosed building area is 17,659 gross square feet.

Question #8: "Is this job tax exempt"

Answer #8: Per the Contract Documents, the Contractor is responsible for paying all applicable taxes and including them in his bid. The project is not tax exempt.

Question #9: "In order for a contractor to bid....do they HAVE to attend the pre-bid meeting Do they HAVE to be on the planholder's list? Or Both?"

Answer #9: Per the Contract Documents, the Pre-Bid was mandatory. Regardless of whether or not a Contractor is on the Plan Holders List, if he did not sign in and sign out of the Pre-Bid, his bid will be marked as non-responsive and not opened.

Question #10: "After further review of the windows, some concerns were raised. If these questions can be answered, it would help me tremendously in going forward in bidding this job. It appears that the anchors are being removed from the bottom of the curtain wall system. Are we responsible for any engineering/warranty of the this work? The removal of anchors, especially the larger opening, will weaken the wind-load of this system."

Answer #10: All window work shall be as indicated on Contract Documents. Contractor shall be responsible for providing a Water Tightness Guarantee per Section 01740 of the Project Manual. The intent of the Contract Documents is to replace the wood sill and sill pan and re-secure. Rather than securing through top of the new sill pan, the details show powder



coated stainless steel anchor straps to be anchored at the face of the blocking to maintain wind resistance. See Drawing Items Note 2 above for additional information.

Question #11: "Will any of the joint plugs or pressure bar be removed and replaced? All we can see is the face cap replacement."

Answer #11: All window work shall be as indicated on Contract Documents. Per details and notes on Contract Drawings, the pressure plate shall be removed, new putty tape installed, and pressure plate reset. The window trim cap cover is also called to be removed and reset following work. See Exterior Repairs Scope of Work Item B2 on Sheet A201 for extent of new cover cap work to replace missing cap.

Question #12: "The caulk joint that is present on the mockup is not in the correct location. Brick is not a conducive substrate to caulk to especially because it's so porous. The caulk or water line should be behind the brick and applied to the water proofing membrane."

Answer #12: The mock-up was for Owner's testing purposes only and is not part of the Contract Documents. There are multiple locations calling for caulk or backer rod and caulk, serving as additional means of protection, and all shall be provided per Contract Documents.

Question #13: "Is it sufficient to say the pan is only there to capture the water that has already passed the critical seal/envelope of the building? The curtain wall system does not need a pan to weep water from the system."

Answer #13: The pan is to capture any and all water draining to sill and shall be installed fully watertight.

Question #14: "If we cannot find an exact match for the pressure bar, will break-metal work as a sufficient substitute?"

Answer #14: No. Per notes and details on Sheet A602, the pressure plate is being removed in order to achieve work and reinstalled. If an existing pressure plate is damaged during construction, it must be replaced to match existing in all respects.

Question #15: "The plans say to salvage doors and frames, so I guess there will be no new doors and frames. Just repair what is there and reuse?"

Answer #15: No. Doors and frames called to be removed on the Demolition Plan shall not be reused in the project. Refer to Sheets D101, A101, and Door Schedule on A601 for existing versus new doors and frames. Also see General Notes on D101 and Demolition Specification Section 02110 for information regarding salvaged items.



ATTACHMENTS:

- 1. Pre-Bid Sign-In Sheet (2 pages).
- 2. Sheet D101 Revision 1 (dated 8.16.2018).
- 3. Sheet A602 Revision 1 (dated 8.16.18).
- 4. Letter from GVA Engineering, L.L.C. dated August 7, 2018 (2 pages).
- 5. Letter from GVA Engineering, L.L.C. dated August 10, 2018 (2 pages).
- 6. Microbiology Analytical Report from QuanTEM Laboratories dated August 9, 2018 (6 pages).
- 7. Microbiology Analytical Report from QuanTEM Laboratories dated August 16, 2018 (3 pages).

<< End of Addendum No. 2 >>

Wednesday, August 1, 2018 10:00 AM

Mandatory Pre-Bid Sign-In Sheet Covington Library Renovation

·· •			Phone	Time in	Time Out
Name	Company	Email Lidalia-Oprivition	985-707-7448	9:35	10:35
Ken Decker	Excalibur	Rjaeckere exclusion	(a) car Hard	9:30-	10:38
· Leslip Masanga	3M	three Migintingerg how com	504 606 1017	1-10 Q'110	10/3/2
3 AILEUS-LAN VENE	1 225	CKELLERQENULIZONMENT	AL. COM 309. 730	47.40	10:00
CAICISTIAN REAL	C. W. L Construction VC	estimating Qarillot ILCCO	n 504.394.5596	9:45	
Dhys Hitt	Excitor constructions	toold so obeing co	504	945	1040
KichelleMeron	Belgencrationt	Jeffelixon edixon	101-570-2018	947	10:20
· Jeff Dixon	Dixon Connecting	Contracting grup (c. con	501 005 4571	9:47	10:30
Donald Gilardon;	Hernondez	bid Oherandez consulting.com	1 JUT JUS 13/1	9.48	10.30 AM
· SHANE CREEN	Cobalt Construction	billy Cobaltine.org	504-557-7255	7.40	10.204
Galler .	a b i c t	1. C. 40- 10- 10-	Tareahon com -	9:50	10:314
	1 Jacob TT STANAGATIA VOISION	TON CREAN COMMERCIAL	ISILE Y AVEL LOUIS	<u>+</u>	
Fred Colopinat	Clescent Ommercia Orsire	C Saven C sallhid-us. com	504- 302 -9200	9:50	10:30
" Steven Gottfrid	Ciescent Commercia (assire Gattfried Contacting LCC	Seven Cgattfried-us.com	504: 302-9200 (9657892-3773	9:50	10:30
"DevenGottfrich "Gorden Gottfrich	Clescent Commercia Consiliere Gottfried Contactinger	Sevenc gottfried-us.com	504 302 -9200 (965) 893 - 3773	9:50 9:50	10:30
10 Steven Gottfriul 11 Gordon Gottfriul 12 MATT HARPON	Gottfried Contacting LCC	Sevenc gottfried-us.com	504-302-9200 (965) 893-3773 985 893-377-2	9:50 9:50 9:50	10:30
10 Steven Gottfriul 11 Gordon Gottfriul 12 MATH HARFN 13 Starla Willowind	Ciescent Commercia (CASIRE Gattfried Contacting LCC 11 4 5 toule - A Development LLC	Sevenegottfried-us.com gordmegottfried-us.com mHazer@csitolid-us.com Steelees-rol-com	504: 302 -9200 (965) 893 - 3773 985 893 - 377 - 985 234-0621	9:50 9:50 9:50 9:50 9:59	10:30 10:30 10:30 10:38

Location 310 W. 21st Avenue Covington, LA 70433

Page 1 of 2

Wednesday, August 1, 2018 10:00 AM

Location 310 W. 21st Avenue Covington, 1A 70433

Mandatory Pre-Bid Sign-In Sheet Covington Library Renovation

Name	Company	Email	Phone	Time in	Time Out	
"Crain Alphanso	Icon Contractors LLC	Craina Orcon contractors, un	504-289-3514	9:55	10:35	
15 Chris Clement	New Orleans 5Tass	abris@ Soviells. com	504-258-7245	7:55	10:40	
15 Brandon Berthelor	MBD Maintenance	bids Embdocharms.com	225-928-5569	9:56	10:36	
"Brandon Simonean	Ashley Smith Const LL	brandows, ascesmal.	Kun 514 416 5991	956	10 90	
18 Doug Danton	Bull Forga Waterprofing	dugdant on Chotmail.con	985-201-4782	1:56	10:39	all
19 Milse NATAI	MNATAL CONTRACTO	OFFRICIA @ MNKtxl. com	985-649-2713	9:55	10:25.	MIL
20 DaviNDlaite	Metro Merch	devices metromechanical	1985-740-2009	9:55	10:38	
21 James Westervell	Sieverding Construction	jones Osieverding construct	, 9 95 -966-4302 Dn	9:55	10:38	
22 Mille Johnson	COMBS CONSTRUCTION	michnishne cm cumbs const	oction com	1:55	10:36	
" Sim Ledet	SLEDET OG WE MENTE	SLEDGTOCUASIGNO	504 780 7330	10,00	10:20	
24 Jared Herstelling	Jobi Roofing Co.	Jarecke i bestrating com	992-2226	10:00	10:35	
* Keith Buch	Roof Tech	Keithe postech-no.con	504-301-5/12	10:00	10:35	
26 TIGER ROUSSELL	CANCERETE BUCTERSOF LA.	TIGEROF AND RETE BUSTERS	514-392-5667	10:00	10:35	
27	5053-def					
28						

Page 2 of 2







HEAD #1 (JAMB SIM) scale: 3"= 1'-0"



HEAD #2 (JAMB SIM) scale: 3"= 1'-0"



HEAD #3 scale: 3"= 1'-0"



HEAD #4 scale: 3"= 1'-0"



<u>JAMB #1</u>

scale: 3"= 1'-0"







scale: 3"= 1'-0"

GENERAL NOTES:

- A. V.O.J. ALL OPENING DIMENSIONS PRIOR TO FABRICATION.
- B. VERIFY WALL ASSEMBLY WIDTH TO ASSURE PROPER FIT INTO THROAT OF HOLLOW METAL FRAME PRIOR TO FRAME FABRICATION.
- C. APPLY BITUMINOUS COATING TO ALL STEEL SURFACES TO BE IN CONTACT (OR CLOSE PROXIMITY) WITH ALUMINUM.
- D. REFER TO BALANCE OF DRAWINGS FOR SPECIFIC INFORMATION ON INSULATION, WALL FINISH, ETC.
- E. ALL DOOR SWINGS SHALL BE AS INDICATED ON PLANS.
- F. THRESHOLD DETAIL AFFECTS EXTERIOR DOOR HEIGHT, PROVIDER SHALL VERIFY EACH CONDITION BEFORE DOOR FABRICATION. NO THRESHOLD (AND COMPLEMENTING BOTTOM OF
- DOOR ACCESSORIES) WILL BE CHANGED DUE TO LACK OF COORDINATION WITH DRAWINGS. G. ALL NEW AND EXISTING HOLLOW METAL FRAMES SHALL BE PREPARED, PRIMED, AND PAINTED PER SPEC SECTION 09900.

Key Notes: (#)

- I. 20 GA. STAINLESS STEEL 2-PART SUB-SILL FLASHING WITH I 1/2" HIGH UPTURNED END DAMS AT JAMBS AND INTERIOR SILL (3 SIDES), ALL JOINTS AND SEAMS WELDED, HEMMED EDGES. MINIMUM I 1/2" OVERLAP BETWEEN PARTS, AND SET IN MASTIC. PAINTED FINISH TO MATCH WINDOW FRAME AT INTERIOR SIDE.
- 2. REPLACE WOOD BLOCKING AT WINDOW SILL WITH PRESSURE-TREATED WOOD MEMBERS.
- 3. EXISTING ALUMINUM CURTAIN WALL SYSTEM PER SCHEDULE.
- 4. EXISTING BRICK VENEER.
- 5. EXISTING CAST STONE SILL.
- 6. EXISTING EXTERIOR SHEATHING.
- 7. EXISTING WOOD BLOCKING AND/OR SHIM.
- 8. EXISTING VAPOR BARRIER. PROTECT FROM DAMAGE. 9. EXISTING HARDWOOD TRIM. REMOVE AND REINSTALL AS REQUIRED TO COMPLETE PROJECT WORK SCOPE. MARK PIECES TO IDENTIFY ORIGINAL LOCATIONS FOR REINSTALLATION. PROVIDE MATCHING
- WOOD PUTTY AT NAILS AND TO CLOSE ALL JOINTS SOLID. IO. EXISTING STUDS.
- II. 20 GA. GALV. STEEL STUD PLATE TIE (MODEL "RSP4" BY SIMPSON STRONG-TIE OR PRIOR APPROVED EQUAL) ATTACHING EACH STUD UNDER WINDOW TO SILL BLOCKING. FASTEN WITH 8d x 1 1/2" LONG NAILS PER MANUFACTURER'S RECOMMENDATIONS. REVIEW CONDITIONS WITH ARCHITECT PRIOR TO INSTALLATION.
- 12. REMOVE AND REPLACE PORTION OF EXISTING GYPSUM AS REQUIRED TO PERFORM NEW WORK (SHOWN CROSS-HATCHED). NEW GYPSUM SHALL BE PATCHED SMOOTHLY AND TEXTURED TO MATCH ADJACENT EXISTING GYPSUM. ALSO SEE FINISH PLAN ON SHEET A401.
- 13. EXISTING GYPSUM (STIPPLED). ALSO SEE FINISH PLAN ON SHEET A401.
- 14. 1/8" DIA. COUNTERSUNK STAINLESS STEEL SCREW WITH HEAD PAINTED TO MATCH WINDOW TRIM CAP. 15. 2-1/2" WIDE 16 GA. STAINLESS STEEL ANCHOR STRAP POWDERCOATED TO MATCH WINDOW TRIM CAP. PROVIDE ANCHOR STRAP AT EVERY VERTICAL FRAMING MEMBER (JAMBS, INTERMEDIATE MULLIONS, Ętc.),
- I6. NEW BACKER ROD WITH CONTINUOUS SEALANT.
- 17. CONTINUOUS SEALANT. ADDENDUM NO. 2-
- 18. EXISTING STEEL LINTEL ANGLE.
- 19. EXISTING FLEXIBLE TRANSITION MEMBRANE (JOB VERIFY). INSPECT TOP TO BOTTOM AND REPAIR ANY BREAKS AND/OR GAPS WITH 40 MIL SELF-ADHERING FLASHING (OVER PRIMED SURFACES).
- 20. EXISTING STEEL TUBE.
- 21. EXISTING STUCCO SYSTEM.
- 22. EXISTING ALUMINUM FLASHING / DRIP EDGE. PROTECT FROM DAMAGE.
- 23. EXISTING METAL PLASTER STOP REMAIN.
- 24. EXISTING SOLID HEADER.
- 25. REPLACE ANY DAMAGED OR WET BUILDING INSULATION IN KIND.
- 26. EXISTING EXTERIOR WINDOW TRIM CAP COVER. PULL AND RESET FOLLOWING WORK. TRIM ENDS WHERE NECESSARY FOR EVEN AND TIGHT FITTING JOINTS. ALSO SEE SHEET A201 FOR REPLACEMENT OF MISSING CAPS.
- 27. EXISTING EXTERIOR PRESSURE PLATE. PULL AND RESET FOR NOTE 28 (PUTTY TAPE REPLACEMENT). 28. FULLY REMOVE EXISTING PUTTY TAPE AND APPLY NEW PUTTY TAPE ("440 BUTYL SEALANT TAPE"
- MANUFACTURED BY TREMCO OR PRIOR APPROVED EQUAL). THIS WORK IS REQUIRED AT ALL MULLION LOCATIONS INCLUDING WINDOW PERIMETER, INTERMEDIATE HORIZONTAL MULLIONS, AND INTERMEDIATE VERTICAL MULLIONS. ALSO SEE EXTERIOR ELEVATIONS AND OPENING ELEVATIONS. 29. EXISTING FLASHING MEMBRANE.
- 30. REMOVE AND REPLACE PORTION OF EXISTING STUCCO SYSTEM AROUND FULL PERIMETER OF OPENING AS REQUIRED TO PERFORM NEW WORK (SHOWN DENSELY STIPPLED), MATCHING EXISTING STUCCO SYSTEM IN ALL RESPECTS. FINISH EDGES WITH J-MOLD. PAINT TO MATCH EXISTING WALL.
- 31. DUCT WORK (AND OPENING SIZE) PER MECHANICAL, SLIGHTLY SLOPED TO DRAIN TOWARD EXTERIOR. 32. THROUGH WALL 22 GA. GALV. METAL SLEEVE (4-SIDED). HEM EXPOSED EDGES. RIVET AND CAULK AT
- MEETING CORNERS. 33. SLOPED 22 GA. PRE-FINISHED STEEL FLASHING AROUND FULL PERIMETER OF OPENING. HEM LEADING EDGE TO CLAMP SLEEVE AND ANCHOR TO HEADER AS SHOWN.
- 34. 2 x 6 TREATED DOUBLE HEADER AND TOP PLATE.
- 35. 40 MIL SELF-ADHERING MEMBRANE WITH END DAMS. INSTALL OVER LINTEL AND ONTO BACK-UP WALL.
- 36. 4" x 4" x 3/8" GALV. STEEL LINTEL AT HEADER ONLY, BEAR 8" ON EACH END.
- 37. REMOVE AND REPLACE PORTION OF EXISTING BRICK VENEER AROUND FULL PERIMETER OF OPENING AS REQUIRED TO PERFORM NEW WORK (SHOWN DENSELY HATCHED).
- 38. FLASH NEW STAINLESS STEEL SUB-SILL PAN INTO ADJACENT WALLS EACH END FOR WATER-TIGHT CONDITION (FLEXIBLE TRANSITION MEMBRANE SAME AS NOTE 19).
- 39. REMOVE EXISTING WALL AS REQUIRED FOR NEW OPENING.
- 40. HOLLOW METAL FRAME PER SCHEDULE (PAINTED).
- 41. DOOR PER SCHEDULE.
- 42. NEW 5/8" GYPSUM BOARD. MODIFY AT EXISTING WALLS AS REQUIRED AND COORDINATE WITH FINISH PLANS.
- 43. NEW 2X DBL WOOD HEADER.
- 44. CAULK, TYP.
- 45. INTERIOR ALUMINUM HEAD/JAMB/SILL.
- 46. WINDOW GLAZING PER SCHEDULE.
- 47. FRAME ANCHOR. TYPE, QUANTITY AND LOCATION PER MANUFACTURER. SECURE TO STRUCTURE AS REQUIRED TO SPECIFIED PERFORMANCE REQUIREMENTS.
- 48. NEW DBL 2X12 @ SILL (HEAD SIM. PER SCHEDULE). SUPPORT ON DOUBLE STUDS EACH END.
- 49. SHIM AS REQUIRED.
- 50. INFILL 2X WOOD FRAMING AT JAMBS.
- 51. DRY WALL "J" TRIM -TYP.
- 52. REMOVE GYPSUM AS REQUIRED TO INSTALL NEW FRAME. MODIFY ADJACENT GYPSUM FINISH AS REQUIRED FOR A NEAT FINISHED CONDITION.
- 53. PROVIDE 2 PVC WEEPS AT HEAD BRICK.
- 54. CONTINUOUSLY CAULK WINDOW TRIM CAP TO JAMB AT BOTH BRICK AND PLASTER, FULL-HEIGHT.
- 55. CONTINUOUSLY CAULK WINDOW TRIM CAP TO HEAD AT BRICK ONLY. 56. PROVIDE FINISH CAP AT EVERY PENETRATION OF FORMER WINDOW ANCHOR LOCATION. SET CAP IN SILICONE AND PAINT TO MATCH WINDOW TRIM CAP.



GVA ENGINEERING, L.L.C.

2615 Edenborn Avenue, Suite C Metairie, Louisiana 70002 Phone (504) 780-9330 Fax (504) 780-9419

August 7, 2018

VIA E-Mail: eorgeron@burgdahlgraves.com

Burgdahl & Graves Architects Attn: Emily Orgeron 2550 Belle Chasse Highway, Ste. 130 Gretna, LA 70053

SUBJECT: St. Tammany Parish Library Covington Branch 310 W. 21st Ave. Covington, LA 70433 Renovations GVA Project No. 3742

Gentlemen:

Please include the following in your next addendum:

PERTAINING TO THE DRAWINGS:

Item No. 1. Sheet No. E-4, Lighting Fixture Schedule

Fixture F7 should read "with 4600 lumen output (minimum)" in lieu of "with 3400 lumen output (minimum)".

PRIOR APPROVAL OF MATERIALS

Listed below are manufacturers who are recognized as capable of producing materials, manufactured items, and articles of equipment equal to those specified. Equipment will be considered acceptable providing the equipment meets, or exceeds specification requirements, has the capacity and performance requirements, fits the space available to the satisfaction of the Architect, conforms in every respect with the applicable regulatory agencies and for lighting fixtures is also similar in appearance, construction and photometrics (photometric information shall be based on independent laboratory reports). Contractor shall submit for approval large scale drawings of proposed layouts and arrangements and samples of lighting fixtures when requested.

The listed prior approvals are not given with respect to any specific model, series, catalog number, etc. Suppliers are cautioned that before their equipment is actually approved, it will be incumbent upon them to demonstrate to the Architect that it is in fact equal to the requirements specified and conforms fully to all specification requirements.

Burgdahl & Graves Architects Attn: Emily Orgeron Project No. 3742 August 7, 2018 Page 2

MATERIAL/EQUIPMENT	MANUFACTURER
F1, F1A, F1AE, F1E	Prescolite, Philips
F2, F2A	Lumenwerx
F3	
F4	Columbia Lighting, Philips
F5	Columbia Lighting, Philips
F6	Columbia Lighting, Philips
F7	Columbia Lighting, Philips
F8, F8A, F8B, F8C,F8D, F8F	
F9	SSL
F10	Columbia Lighting, Philips
Exit	Dual Lite
Lighting Controls	Leviton

Sincerely,

GVA ENGINEERING, L.L.C.

en ledet Sim Ledet

GVA ENGINEERING, L.L.C.

2615 Edenborn Avenue, Suite C Metairie, Louisiana 70002 Phone (504) 780-9330 Fax (504) 780-9419

August 10, 2018

VIA E-Mail: eorgeron@burgdahlgraves.com

Burgdahl & Graves Architects Attn: Emily Orgeron 2550 Belle Chasse Highway, Ste. 130 Gretna, LA 70053

SUBJECT: St. Tammany Parish Library Covington Branch 310 W. 21st Ave. Covington, LA 70433 Renovations GVA Project No. 3742

Gentlemen:

Please include the following in your next addendum:

PRIOR APPROVAL OF MATERIALS

Listed below are manufacturers who are recognized as capable of producing materials, manufactured items, and articles of equipment equal to those specified. Equipment will be considered acceptable providing the equipment meets, or exceeds specification requirements, has the capacity and performance requirements, fits the space available to the satisfaction of the Architect, conforms in every respect with the applicable regulatory agencies and for lighting fixtures is also similar in appearance, construction and photometrics (photometric information shall be based on independent laboratory reports). Contractor shall submit for approval large scale drawings of proposed layouts and arrangements and samples of lighting fixtures when requested.

The listed prior approvals are not given with respect to any specific model, series, catalog number, etc. Suppliers are cautioned that before their equipment is actually approved, it will be incumbent upon them to demonstrate to the Architect that it is in fact equal to the requirements specified and conforms fully to all specification requirements.

MATERIAL/EQUIPMENT	MANUFACTURER
F3	ASL Lighting
F8, F8A, F8B, F8C,F8D, F8F	Hubbell Lighting LiteControl
Water Closet	Western Pottery
Lavatory	Western Pottery
Urinal	Western Pottery

T:\JOBS\3700's\3742\Correspondence\08-10-2018.ADENDUM ITEMS.BGA.EO.dcc.wpd

Burgdahl & Graves Architects Attn: Emily Orgeron Project No. 3742 August 10, 2018 Page 2

Faucets	Delta
Supply valves	Brasscraft
Water Closet Seat	Plumbtech

Sincerely,

GVA ENGINEERING, L.L.C.

Scott Oestriecher



2033 Heritage Park Dr, Oklahoma City, OK 73120 | 1.800.822.1650

Microbiology Analytical Report (Results)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc	
Date Received:	08/09/2018		11628 S. Choctaw Dr	
Received By:	Travis Miller		Baton Rouge, LA 70815	
Analyzed By:	Terry Harrison			
Date Analyzed:	08/09/2018	Account Number:	C187	
Methodology:	Bulk, Qualitative NonCulturable,	Project:	Covington Branch Library	
	MM003, MM004, MM005	Location:	310 W 21 ave. Covington, LA	
AIHA ID Number:	101352	Project No:	1008-0001	

QuanTEM Sample ID	297694-001	297694-002		
Client Sample ID	1008-0001-01	1008-0001-02		
	Results	Results		
Cladosporium	Abundant	Abundant		
Hyphal Fragments	Moderate	Moderate		
Comments				



2033 Heritage Park Dr, Oklahoma City, OK 73120 1.800.822.1650

Microbiology Analytical Report (Signature Page)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc
Date Received:	08/09/2018		11628 S. Choctaw Dr Batan Bauga LA 70815
Received By:	Travis Miller		Baton Rouge, LA 70815
Analyzed By:	Terry Harrison		
Date Analyzed:	08/09/2018	Account Number:	C187
Methodology:	Bulk, Qualitative NonCulturable,	Project:	Covington Branch Library
	MM003, MM004, MM005	Location:	310 W 21 ave. Covington, LA
AIHA ID Number:	101352	Project No:	1008-0001

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA-LAP, LLC. or any agency of the U.S. Government.

Approved: Jawen Comeren

Lauren Cameron, Technical Manager



2033 Heritage Park Dr, Oklahoma City, OK 73120 | 1.800.822.1650

Microbiology Analytical Report (Results)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc		
Date Received:	08/09/2018		11628 S. Choctaw Dr Batan Bauga LA 70815		
Received By:	Travis Miller		Baton Rouge, LA 70815		
Analyzed By:	Terry Harrison				
Date Analyzed:	08/09/2018	Account Number:	C187		
Methodology:	Spore Trap, Quantitative NonCulturable,	Project:	Covington Branch Library		
	MM001	Location:	310 W 21 ave. Covington, LA		
AIHA ID Number:	101352	Project No:	1008-0001		

QuanTEM Sample ID	297694-003	297694-004	297694-005	297694-006	297694-007	
Client Sample ID	1008-0001-03	1008-0001-04	1008-0001-05	1008-0001-06	1008-0001-07	
Volume (L)	150	150	150	150	0	
Detection Limit	7	7	7	7	0	
	Results	Results	Results	Results	Results	
	Counts/m ³					
Alternaria	20			13		
Arthrinium	7					
Ascospores	17400		47	10593		
Aspergillus/Penicillium Group	153	1067		167		
Basidiospores	480	7		353		
Bipolaris/Drechslera Group (2)	7			13		
Cercospora	7					
Cladosporium	587	400		427		
Curvularia	7	7	7	40		
Helicomyces				7		
Hyphal Fragments	47	47	13	53		
Mildew	7					
Nigrospora	13		7	33		
Paecilomyces	87					
Periconia/Myxomycetes/Smuts	13	7		13		
Pithomyces/Ulocladium	7					
Rusts	100					
Spegazzinia	33					
Torula	7					
No Mold Detected					Х	
Total Results (Counts/m ³)	18982	1535	74	11712		
Percent Coverage (%)	5	3	2	5	1	
Comments					No Mold Detected	



2033 Heritage Park Dr, Oklahoma City, OK 73120 | 1.800.822.1650

Microbiology Analytical Report (Counts)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc	
Date Received:	08/09/2018		11628 S. Choctaw Dr Patan Pauga LA 70815	
Received By:	Travis Miller		Baton Rouge, LA 70815	
Analyzed By:	Terry Harrison			
Date Analyzed:	08/09/2018	Account Number:	C187	
Methodology:	Spore Trap, Quantitative NonCulturable,	Project:	Covington Branch Library	
	MM001	Location:	310 W 21 ave. Covington, LA	
AIHA ID Number:	101352	Project No:	1008-0001	

QuanTEM Sample ID	297694-003	297694-004	297694-005	297694-006	297694-007	
Client Sample ID	1008-0001-03	1008-0001-04	1008-0001-05	1008-0001-06	1008-0001-07	
Volume (L)	150	150	150	150	0	
	Counts	Counts	Counts	Counts	Counts	
Alternaria	3			2		
Arthrinium	1					
Ascospores	2610		7	1589		
Aspergillus/Penicillium Group	23	160		25		
Basidiospores	72	1		53		
Bipolaris/Drechslera Group (2)	1			2		
Cercospora	1					
Cladosporium	88	60		64		
Curvularia	1	1	1	6		
Helicomyces				1		
Hyphal Fragments	7	7	2	8		
Mildew	1					
Nigrospora	2		1	5		
Paecilomyces	13					
Periconia/Myxomycetes/Smuts	2	1		2		
Pithomyces/Ulocladium	1					
Rusts	15					
Spegazzinia	5					
Torula	1					



2033 Heritage Park Dr, Oklahoma City, OK 73120 1.800.822.1650

Microbiology Analytical Report (Signature Page)

QuanTEM Lab ID:	297694	Client:	SEMS, Inc
Date Received:	08/09/2018		11628 S. Choctaw Dr Paton Pougo I A 70815
Received By:	Travis Miller		Batoli Kouge, LA 70815
Analyzed By:	Terry Harrison		
Date Analyzed:	08/09/2018	Account Number:	C187
Methodology:	Spore Trap, Quantitative NonCulturable,	Project:	Covington Branch Library
	MM001	Location:	310 W 21 ave. Covington, LA
AIHA ID Number:	101352	Project No:	1008-0001

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

(1)Small, single-celled, unidentifiable mold spores (2)Also includes spores from Exosporium, Exserohilum and Helminthosporium

Percent coverage = amount of particulate matter. With 25-50% coverage, results may be underestimated; with 50-70% coverage, results will be underestimated; with >70% coverage, slides are designated overloaded (too dirty to count). The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA-LAP, LLC. or any agency of the U.S. Government.

Approved: James Comeser

Lauren Cameron, Technical Manager

		MICROBIOLO	D Y DC	HAIN O	JF CUSTO	ŊŊŶ	Pag	le 1 of <u>7</u>
		2033 Heritage Par	k Drive, Ok	dahoma City	, OK 73120-7502		For	Lab Use Only
LABORATOR		 0C01-770 (000) 		-/2/2	2007-00/ (00+) .		Lab No.	45 X 52
www.QuanTEM	.com	LEGAL DOCU	- TNEM	PLEASE P	RINT LEGIBL	Y		Accept Reject
Cont	act Information				Project	Information	Report R	esults (🗹 one box)
Company: SEMS, Inc.		Phone: 225-408-28	60	Project Name: 🤇	ovington	Parch Libry	Dua Dua	inTEM Website
contact: Phillip Bellan		Cell Phone: 225-588-90	66	Project Location:	310 W 21	ave councien Ut	F Ema	ail pbellan@semsinc.net
Account #: C187		E-mail: pbellan@serr	nsinc.net	Project ID: 10	1 000-80	l al anno 1	Oth	er
SAMPLED BY: Name: Phill: BA	lar	Date: 8-8-18		P.O. Number:)	t 00-80	S.		
RELINQUISHED BY	State Provention	DATE & TIME	>	'IA		RECEIVED BY		DATE & TIME
alle a		00:91-811-8-8	Feder	8	?A	Mr. 1558-9 9:45		
		REQUESTED SERVIC	CES (Plea	ise 🗹 the A	ppropriate Bo	xes)		
Fungal Analysis (non-culture)	Fungal Analys	is (non-culture)	ungal An	ialysis (cult	ure based)	Bacterial Analysis	TUŘ	NAROUND TIME
Spore Trap	Bulk/Swab		Impacti	on Plate		Water Screen		Rush
Spore Trap (Detailed)	Bulk/Swab (Qu	antitative)	Sedime	ntation Plate		Sewage Screen		Same Day
Tape Lift	Other (Specify	in Comments)	Bulk/Sw	/ab - Genus ID		Heterotrophic Plate Count		24 - Hour 3 - Davi
Tape/Lift (Quantitative)			Bulk/Sw	/ab - Genus ID 8	k Enumer.	Heterotrophic Plate count with ID		5 - Day
			Other (S	Specify in Comr	nents)	Other (Specify in Comments)		14 - Day (Cultures)
No. Sample ID (10 Characters Max)	Descr	iption	Volu (as a	ume / Area applicable)		Media / Comments / I	Notes	
1 1008-0001-01 The list	th too vor the	Ceiling non ficti	23	"x 2"	+ upe 1:41 /	69.90 F @ Sunt.	locelta	
2 -0, Thin 1:	It to varited	ceilin chidren.	21	11	1 1	11 @ SAmply	locatio	
3 - 62 outside	T: Front	dae-	15	70	0:1-0-12/1	Jott ,		
4 - 04 company	+ i adult f	iction / tren redie	151	70	11	64.40F		
5 -05 non-low	doint : public	consuler room	150	26	1 11	63.6°F		
6 -06 outside	2: outside	endorer extents	15	10	/ N.	24.6'F		
7 cot Block			,	١	[9			
8								a
6								
10								
SATURDAY FEDEX SAMPLE DELIVERY - CI	ALL TO SCHEDULE	Use this address for Sature	day Delivery	only: 4220 N.	Santa Fe Ave., Okl	ahoma City, OK 73105-8517 💿 Mark	k Package "He	old for Saturday Pickup"

Please Note - UPS and USPS are NOT available for Saturday Delivery



2033 Heritage Park Dr, Oklahoma City, OK 73120 | 1.800.822.1650

Microbiology Analytical Report (Results)

QuanTEM Lab ID: Date Received: Received By: Analyzed By:	298002 08/16/2018 Travis Miller Terry Harrison	Client:	SEMS, Inc 11628 S. Choctaw Dr Baton Rouge, LA 70815
Date Analyzed:	08/16/2018	Account Number:	C187
Methodology:	Swab, Qualitative NonCulturable, MM003, MM004, MM005	Project:	Covington Library
		Location:	310 S. 21 Covington, LA
AIHA ID Number:	101352	Project No:	1008-0001

QuanTEM Sample ID	298002-001	298002-002	298002-003		
Client Sample ID	PC-01	PC-02	PC-03		
	Results	Results	Results		
No Mold Detected	Х	Х	Х		
Comments	No Mold Detected	No Mold Detected	No Mold Detected		



2033 Heritage Park Dr, Oklahoma City, OK 73120 1.800.822.1650

Microbiology Analytical Report (Signature Page)

QuanTEM Lab ID:	298002	Client:	SEMS, Inc
Date Received:	08/16/2018		11628 S. Choctaw Dr Paton Pougo LA 70815
Received By:	Travis Miller		Baton Rouge, LA 70815
Analyzed By:	Terry Harrison		
Date Analyzed:	08/16/2018	Account Number:	C187
Methodology:	Swab, Qualitative NonCulturable,	Project:	Covington Library
	MM003, MM004, MM005	Location:	310 S. 21 Covington, LA
AIHA ID Number:	101352	Project No:	1008-0001

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA-LAP, LLC. or any agency of the U.S. Government.

Approved:

Robin Brady Naik, Analyst

	1	MICKOBIOLO	GY CH	AIN OF CUSIC	λD	Page 1 of <u>1</u>
		2033 Heritage Park (800) 822-1650	Drive, Oklaho	oma City, OK 73120-750	2	For Lab Use Only
LABORATO	R I E S				,	Lab No. 25 FUCUZ
www.QuanTf	EM.com	LEGAL DOCUI	MENT - PLE	EASE PRINT LEGIBI	Y	Accept Reject
S	ntact Information			Project	Information	Report Results (🗹 one box)
Company: SEMS, Inc.		Phone: 225-408-280	9 Proje	ct Name: Covincter	ribar,	QuanTEM Website
Contact: Phillip Bellan		Cell Phone: 225-588-906	6 Proje	ct Location: 3/0 5.	21 County UA	Email pbellan@semsinc.net
Account #: C187		E-mail: pbellan@sem	sinc.net Project	til: 1008 - 00	20 00	Other
SAMPLED BY: Name: Phillip	Bella	Date: 8-15-18	P.O. N	umber: 100 8 - 00	100	
RELINQUISHED	ВҮ	DATE & TIME	VIA		RECEIVED BY	DATE & TIME
my ll		8-15-18 19:00	Feder			
		REQUESTED SERVIC	ES (Please E	☑ the Appropriate B	oxes)	
Fungal Analysis (non-culture)	Fungal Analys	sis (non-culture) Fu	ingal Analys	is (culture based)	Bacterial Analysis	TURNAROUND TIME
Spore Trap	Bulk/Swab		Impaction Pl	ate	Water Screen	Rush
Spore Trap (Detailed)	Bulk/Swab (Qu	antitative)	Sedimentatio	on Plate	Sewage Screen	Same Day
Tape Lift	Other (Specif)	/ in Comments)	Bulk/Swab - (Genus ID	Heterotrophic Plate Count	24 - Hour 3 - Dav
Tape/Lift (Quantitative)			Bulk/Swab - (Genus ID & Enumer.	Heterotrophic Plate count with ID	5 - Day
			Other (Speci	fy in Comments)	Other (Specify in Comments)	14 - Day (Cultures)
No. Sample ID (10 Characters Max)	Descr	iption	Volume (as appli	/ Area cable)	Media / Comments / N	Votes
1 PL-01 Non	-fidium 811 a	acc - ceiling	150	H. Post clea	in - no visith mold	detectol
2 PL-02 Child	1100 0000	ceilia	1 54	FL. 11		
3 91-03 1310	ah -		- 1	(
4						
5						
9						
7						
8						
6						
10						
SATURDAY FEDEX SAMPLE DELIVERY	 CALL TO SCHEDULE 	Use this address for Saturd	ay Delivery only	: 4220 N. Santa Fe Ave., Ok	lahoma City, OK 73105-8517 Mark	<pre>k Package "Hold for Saturday Pickup"</pre>

.

Please Note - UPS and USPS are NOT available for Saturday Delivery

20 ((1 C AINI ンン C ICIOCOUIV



August 10, 2018

Please find the following addendum to the below mentioned BID.

Addendum No: 1

Bid No: 333-00-18-21-2

Project Name: Covington Library Renovation

Bid Due Date: Thursday, August 30, 2018

GENERAL INFORMATION:

1. Please note that the Bid Opening has been pushed to Thursday, August 30, 2018. Time and location remains the same. The last day to submit written inquiries is Tuesday, August 21, 2018 at 2:00 PM.

End of Addendum #1